S1/4 Cor Sec 16-103-14

2002 JHS Crew Searched area and found no Evidence of the original PLS Cor.
Set a 5/8" ø capped 13807 on South Edge of Wooden Corner Fence Post of 3-Way Fence Intersection

9-16-02
30°
CPV
GKB

52

