N¼ cor SEC. 30-103-14

NO CORNER INFORMATION AVAILABLE FROM MOWER Co. SURVEYOR.

AFTER EXTENSIVE TRAVERSE PART of which IS SHOWN ON NEXT PAGE, AND SEARCH of THE CORNER AREA. NO EVIDENCE of A MONUMENT of ANY KIND WAS FOUND.

WE SET A 3/4" IRON PIPE FOR CORNER.

"NOTE" COPYED FROM JERRY SCHWARTZ NOTE'S.

7-27-88 HLS

32

