E¼ Cor Sec. 6-103-15

6-13-80 Ray Trenkler
Dug corner and found
2.5' Long Steel Pipe
Reset Pipe location
Placed Standard Co. Mon.
½" Rebar W. 88.85'
½" Rebar NE - 100.0'
½ Rebar SE - 96.00'
Shows corner 5' West of ℄

JHS crew Dug with Mowers ℄
Backhoe, Dug at county Dist
of 2653.0 from SE cor. on
straight line. Dug a 10'x15'
Hole, and Found No Evidence
of 2.5' pipe.
Set corner on straightline
Between SE cor and NE
At a Dist of 2653.0. From
SE cor.

CPV Date? Set Alum Mon (After New Const.)
HLS 1-19-04 Mon. Distroyed - Needs to
be Replaced & tied off.
8-3-06 Found ⅝" Ø & Shot w/GPS.

8-18-02 Cloudy 70 HLS SAT 35

