S ¼ cor SEC. 5 - 103 - 15

No Information Found in Mower Co. Corner Records

JHS Crew Located Large Spk. Bent. on C Tw Rd. And in Line with Field Division and Line Fence South.

Ray Tuckner did Farm Bldg Survey in S½ SE¼ Sec. 5-103-15. Checked into his pins. And Found that he used a straight Line between SE cor & SW cor of Sec. 5-103-15

Found Mile. to be 5298.30 Held straight Line, And Replace Spk. Found with Cap 5/8" & 13807.

8-22-06 JAS Crew Visited this Loc & Found that Cor had been Destroyed Computed Loc. using 1-19-04 Info as Shown in DWC.

1-19-04 Cloudy 20° HLS TLM 47

