W1/4 Cor Sec 12-103-15

Cert. Filed by JHS 7-12-96

Found CIM LS

Ray Tucker Cert 1984

HLS
MHS

9-9-05 Tied of Corner 50' N. 50' So.
SPK's - (Monument Placement)

7-25-06 RESET CORNER HLS MOH
PLACED CORNER MARKER

8-2-06 Found survey MARKER : SHOT W/GPS.

4-25-91 DRR 2.

