S¼ cor SEC. 8-103-15

Cert. filed by JHS 1-9-97

No Information Found in Mower Co. Records.

	SE cor of SEC. 8	Fd CJH
BKST	SW cor of SEC.	Fd CJH
	528456	

HLS MHS

9-9-05 Tied of Corner –

5/8"ø N.	50.0
5/8"ø So.	50.0

JHS Crew Dug with Mower Co. Backhoe. Dist. From SW cor to SE cor being 5284.57.

Set Point @ split between SE & SW corners on straight line

Point Fits Field Divisions N & S.

8' North of Center Line of Road.

Dug a 3'x6'x5' deep hole, Found No Evidence of PLS corner.

Set Corner @ split 2642.28

Set ⅝"x16" Iron with Cast Iron Mon. 40 Below Road Surface.

7-25-06 RESET CORNER HLS MHS

PLACED CORNER MARKER

7-29-06 MHS AKD FOUND CORNER MARKER SHOT WITH GPS FOR BASEMAP

8-1-96 CLEAR 80° HLS JRS

19

