E 1/4 Cor Sec 36-103-15

2002 JHS Crew Dug by hand at location of signal from Magnetic locator and uncovered a P.K Nail on Road surface. Continued digging and found a concrete Monument with an Iron pin 0.7' below road surface.

7-11-02

CPV
MWE

31

