8-27-91 1 ✓

E¼ Cor Sec 11-103-16.
Cert. Filed 9-17-91 by JHS
Dug with Co. backhoe on ℄ N-S Road in line with fence east and uncovered a harrison CIM over (2) 5/8"ø irons extending 4" below road surface, found no further evidence of PLS Corner reset CIM

