NW cor SEC. 33-103-16

NO Information Found in
Mower Co. Corner Records

5-5-80
SEE Book- 237 pg 34
Fd 5/8" ø (Plated Spk-Outer)

JHS Crew Dug with Mower
Co. Backhoe on E & W twp Rd
N-S & E-W - uncovered
Spk. at Rd Surface.
Continued Digging And
Found 2" Iron at 1.5 ±
Below Road Surface.
Dug Along side of 2" Iron
And Found other Iron Below.
Accepted Iron's as True
PLS Corner. Left Irons
As Found.
Set 5/8" x 16" Iron with
Alum Mon. Outer Irons Found
.60 ± Below Rd. Surface.
Spk. Found on Surface 150 West
And 1.6' N. of Irons Found.

9-10-02
Cloudy
>50°
HLS
EPB
47

