E 1/4 Cor Sec 34-103-16

See Book 208 pg 40
Fd Spike & N-S Rd
See Section Breakdowns and 33+34

8/5/05 Fd Spike & of Road in Line with Fd Div West

JHS Crew dug with RAY TUCKER Backhoe, At Location Spike Found. Dug down to Virgin Soil and Found No other Evidence of PLS Corner.

Set 5/8" x 16" Iron with Cast Iron Mon. in Place of Spike, .60± Below Rd. Surface

8-15-05
Cloudy
80°

HLS
MHS

