✓

E 1/4 Cor Sec 7-103-17

Found no evidence of PLS corner or a perpetuation of therefore set CIM on line between SE & NE Sec Cor's and the mid point

