NW Cor Sec 16-103-18

Cor destroyed by open ditch construction.

Computed position in line with fence South and by doubling over 16th fence line in NE 1/4 section 17.

