E ¼ Cor SEC. 24 – 103 – 18

Cert. Filed by JHS 1-27-97

Mower Co. Records State.

Iron Pipe & Stone in Place.

1954 Corner was Located. INP Iron Pipe 12" Below Rd. Surface.

Took New Ties,

Tie to NE PP 65.4' –

1973 INP Iron pipe – 12" Below Rd. Surface

Bk. 157-Pg 44 69.6' S. SW To Blazed 12" Pine
50.5 S. To 8" CFP
59.9 NW To TP.

2-6-95 JHS Crew dug Corner by Hand Found a Capped ⅝" Iron (No. 1380) on ℄ of CSAH No. 16 & ℄ of Twp Road North. Removed Cap and Set Cast Iron Mon over ⅝" Iron Found .30 Below Road Surface. 1954 Tie Check to NE PP.

2-6-95
Cloudy
20°

JHS

43

