SE COR SEC 13-103-10

Cert. Filed 12-27-95 by JHS

SPK/W ON EAST SIDE BRIDGE DECK ℄ ON ℄ E-W CREEK, THIS PT IS SET ON ST. LINE BETWEEN E¼ COR SEC 13 & E¼ COR SEC 24 & ∅ INTER WITH FENCE LINES EXTENDED FROM PK/W

HLS & JPA.

2-6-95 REMOVED SPK/W. SET CAPPED ⅝" IRON CAP INC 13807.

Cor. marks ~~to 6&8~~ moved 2.28' ERROR 8-26-24-77 SJT

8-26-99 RESET CORNER, SET ⅝"X16" IRON WITH CAST IRON MKR, CORNER DESTROYED INSTALLING NEW -CALLOUTS

SEE Red Rock TIE Book pg. 77 & 78.

7-12-94 PC +'85° JHS TRS

16

