1/4 cor SEC 8-104-14

NO INFORMATION
FOUND IN MOWER Co. RECORDS

JHS CREW LOOKED OVER AREA. CORNER WOULD HAVE BEEN DESTROYED AT TIME of Bridge Const.

JHS CREW COMPUTED LOCATION OF 1/4 COR TO BE ☐ MIDPT BET. NE & SE CORS OF SEC 8- THIS LOC FITS FENCE LINE OU SO LINE W1/2 NE1/4 SEC 9

