NE cor SEC. 14-104-14

No Information in Mower Co. Corner Records

9-4-03 JHS crew dug by hand at location of signal from location. Uncovered ½" iron .60± deep.

8-21-06 AKP EJL Found cim & shot w/GPS.

8-21-06 JHS crew dug with Ray Tucker backhoe at location of ½" iron. Removed iron and dug down below, and found no other evidence of PLS corner. Replaced ½" iron as found set ⅝"x16" iron with cap Iron Ouen, ½" iron found 60± below RS surface.

9-4-03 Cloudy 75° HLS Tam 49

