NW Cor Sec 15-104-15

cert. Filed 5-6-91 by JHS

Dug on ℄℄ N-S-E road for bridge project # L5062

Dug a 4'x12'x5' deep hole and found nothing, stone must have been destroyed during road const. that is noted in BK "A" in the Co. Eng. office set CIM on ℄℄ as best evidence

7-24-06 FOUND CIM & SHOT W/GPS.

4-25-91 DRR/RMK 1.

