SW Cor Sec 15-104-15

Cert. Filed 5-6-91 by JHS

Dug with Co. backhoe on CL for bridge project # L5062

Dug a 4'x6'x6' deep hole and found nothing, 1954 records in BK "A" in Co. Eng. office shows a conc. mon. in place over a stone which was reset in 1939, using ties from 1954 survey set CIM 0.5' below road surface

7-25-06 FOUND CIM & SHOT W/GPS.

4-26-91 DRR/RMK 2.

