E 1/4 Cor Sec 9-104-16

No Information found in Mower County Records

8/20/05 Nothing Fd -
Set Temp spike @ location of split ±
Fit remaining Fld Div West Property owner to the NW said it fits where he was told corner is located

JHS CREW dug with RAYTHEON BACKHOE, At Location of SPIKE, Dug a 4.5' ± x 15' Long HOLE, AND Found NO EVIDENCE of PLS CORNER.

11/11/05 Set corner on ¢ of Road equidistant between corners
Position Fit Fld Division to West ¢ OCC ⇝ CNT OF SECTION

10-3-05
Cloudy
75°
HLS
MHS
24

