E 1/4 Cor Sec 10-104-16

SEE Bk 315 pg 21-22
Did not use corner for survey
used straight line between NE
+ SE corners

County Road Plan 1972 shows 1/4 line
fence @ STA 366+30
SE corner @ STA 340+00.7
NE corner @ STA 393+17.5

8/22/05 Nothing found in field - Field Div. East
@ approximately 2630'± North of SE
corner

11/11/05 Computed position from 1962
Road Plan @ a proportional
foot Distance from NE + SE
corners on a straight line between
corners. Fit Field Division East

No monument Set

SEE: Corner Certificate filed by
Westwood Professional Services
dated 2-4-14

