SW¼ cor SEC. 10-104-16-

NO INFORMATION FOUND
IN MOWER CO. CORNER RECORDS

THIS CREW DUG with MOWER
CO. BACKHOE, UNCOVERED ¾"x1'
IRON (BENT). CONTINUED DIGGING
to VIRGIN SOIL AND FOUND
NO OTHER EVIDENCE of PLS
CORNER.
SET ⅝"x16" IRON in
PLACE of BENT ¾"x1' IRON
FOUND. with CAST IRON MON
-.60 ± BELOW ROAD SURFACE.

8/16/65 Fd 5/8" ø Bent to the East w/no CIM
5/8" Fit Ties Reset CIM on 5/8" ø

8-10-01
PC
75°

HLS
SAT

56

