E 1/4 Cor Sec 34-104-16

MOWER CO 1930 ROAD QUAD SHOWS NO COR @ THIS LOC, & THAT ROAD CURVED AROUND 1/4 COR LOC.

[SET E 1/4 COR ON LINE BET. NE COR & SE COR IN LINE WITH FLC TO EAST.]

IN 1930's THE ROAD WAS REGRADED ON ST LINE BET SEC CORS & A NEW BRIDGE INSTALLED WHICH WOULD HAVE DESTROYED ALL EVIDENCE OF PLS COR

