E¼ Cor SEC. 35-104-16

NO INformation Found.
IN Mower Co. Corner Records

1000.60
1659.92
2660.52 V.S 2665

JHS CREW Dug with Mower Co.
Backhoe. AT Location of
Signal From Location.
UNCOVERED 1" PIPE, Dug
DOWN ON EAST side of Pipe.
AND Found NO OTHER Evidence
of PLS CORNER, ACCEPTED PIPE
AS CORNER, LOWERED PIPE AND
SET ⅝"x8" IRON with
CAST IRON MON. OVER PIPE

6-13-02
Cloudy
70°
HLS
SAT

66

