W¼ cor SEC. 4 - 104 - 17

SEE: Corner Certificate filed by Whitwood Professional Services dated 2-4-14

Dodge 4WD Ctm 60.2 mounds CRS

NO Information Found in Mower Co. Corner Records

JHS CREW Look over AREA - Found 2 - 24" Plastic Pipe Crossing road where corner would be Located. Corner would have been destroyed.

SET Corner in Centerline Twp Rd. and in line with Line Fence East

SET ⅝" x 16" Iron with Alc Pol Cap Iron over

Scribe 3592.25 .60± BELOW FS NW cor Road Surface

D 1693.54

FS 16th Line N± East

D 375.74

FS W¼ cor

D 951.14 ~~952.92~~ 949.36

18+17.80

13+17.89

19+25.09

26+42.89

52+68.19

26+42.89

CTM

5-19-05 Cloudy 70° HJS EJL

SEC. 5-104-17

SEC. 4-104-17

⅝" Iron Skid 50.0'

24" Plastic

24" Plastic

32.30'

Spkw in Cff

50.0

⅝" Iron Skid

SEC 5-104-17

SEC. 4-104-17

16th Line