W 1/4 Cor Sec 22-104-18

No Information was Found In TH #56 Road Plan

JHS Crew Computed Position by intersecting a straight Line Between the NW & SW Sec Corners and an Extention of the Fence Line From the East.

- No Monument was Set.

2-19-03

