SE Cor Sec 19-104-18

JHS Crew located Corner During Section Breakdown work.

SEE Book 377 Page 20

