E¼ cor SEC. 26-101-14

6-25-40 Cor set by Ray Tucker
Placed CIM 6" Below
Rd Surface. ½" Iron Below.

12-31-03 THS CREW LOCATED CORNER.
TOOK NEW TIES.

5-11-04 Reset Monument after Regrading
CPV Project Using GPS.
EJL Set a survey pin @ this location.

12-31-03
Cloudy
30°

HLS
TLM

46

