E¼ cor SEC. 30-101-14

NO INFORMATION FOUND MOWER CO. RECORDS.

DRR PLACED SPK. @ APPROXIMANT ESTIMATED LOCATION.

THS CREW dug by HAND @ LOCATION of SIGNAL FROM LOCATOR, FOUND ⅝"ø .20 BELOW ROAD SURFACE. COULD NOT LOCATE SPK.

THS CREW DUG with MOWER CO. BACKHOE, on ℄ of TWP ROAD. UNCOVERED ⅝"X 2' IRON. CONTINUED DIGGING AND FOUND NO OTHER EVIDENCE of PLS CORNER. LEFT ⅝"X 2' IRON AS FOUND. SET ⅝"X 16" IRON with CASTIRON MON OVER ⅝"ø FOUND. FOUND SPK/W IN FC POSTS, RE USED FOR TIES.

8-7-97
CLEAR
75°

HLS
TRS

23

