SE COR SEC 28-101-14

8-12-81 CERT. SHOWS NO EVIDENCE OF PLS CORNER, PLACED 4" DIAMETER CAST IRON MARKER STAMPED SECTION CORNER OVER CONCRETE MARKER

8-9-6 SHS CREW FOUND SURVEY MARKER AT ROADSURFACE. TIES FIT

