SE cor SEC. 12-103-17
Cert. fld by THS 1-26-96
No Information Found in
Freeborn Co. Records

10-27-95 THS CREW dug with Freeborn Co. Backhoe on ℄ of Twp Rd ℄ in Line with Field Division East. Dug a 15'x 4' hole 5.50' deep. And Found No Evidence of PLS Cor.

Set 5/8"x16" Iron with cast Iron Mon on ℄ of Road ℄ in Line with Field Division East, At a distance of 2640.0' From E¼ cor to SE cor.

