Index No. _____

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

S1/4 Corner of Section 28, Township 101N, Range 16W, 5TH P.M.

STATE OF MINNESOTA, County of MOWER


At the corner location shown on the sketch:

☐ On 6-4-93 (DATE) found a MAGNETIC DISC AND A 6"ø CLAY TILE FILLED WITH CONC, AND A 3/8"ø IRON IN CNT

☐ left monument as found, ☐ lowered monument, ☐ removed monument (explain)

☐ On 6-4-93 (DATE) placed a CAST IRON MONUMENT

SKETCH OF REFERENCE TIES



JONES, HAUGH & SMITH INC.
Civil Engineers & Land Surveyors
Albert Lea, Minnesota

Statement of evidence relative to this corner location is on back of page.

I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.

_____ (SIGNATURE) 6-18-93 (DATE)

Registration No. 13807

☐ Land Surveyor, ☐ Professional Engineer

☑ County Surveyor, ☐ County Engineer

OFFICE OF THE COUNTY RECORDER
County of Mower

I hereby certify that this document was filed in the County Rec. office at 8 P.M. on the 25 day of June, A.D., 1993

COUNTY RECORDER Amanda Enger

By Marlene Martin, Deputy

DOCUMENT NO. 121440 Bk 80 Pg. 131

M.H.D. FORM NO. 2105

BOOK 80 PAGE 131

STATEMENT OF EVIDENCE

S 1/4 cor Sec 28-101-16

This corner was originally established by Deputy Surveyors Charles Phipps and Edward Fitzpatrick of the U.S. General Land Office in 1853. The government notes show a stone was set with a mound of earth and trench.

The following were contacted for section corner information:
Mower County Highway Department
Mower County Recorder
Zenk Engineering
Tucker Land Surveying

The following information was obtained to support evidence of the perpetuation of the original public land survey corner.

1891 Clausen, Mower County Surveyor, notes indicate a government post at this corner 40.32 chains west of the southeast corner of Section 28-101-16.

1956 Mower County Highway Department Book 1 notes indicate a concrete monument inplace.

1956 Mower County Highway Plans show a magnetic monument inplace.

1993 Jones, Haugh & Smith Inc crew under the direction of John H. Schulte IV, RLS 13807, dug a 3'x2'x8' hole on the centerline of County State Aid Highway No. 6 and in line with north-south line fences. We found a magnetic disc 6" below road surface and a 6" diameter clay tile filled with concrete and a 3/8" diameter iron in center two feet below road surface. Therefore we accepted clay-concrete monument as the perpetuation of the public land survey corner and left in location found and set a cast iron monument near road surface above clay-concrete monument found.

The monument found and cast iron monument set fits occupation lines within the section and is accepted as best evidence of a perpetuation of the original public land survey corner.