Index No. _____

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

W1/4 Corner of Section 28, Township 102N, Range 17W, 5th P.M.

STATE OF MINNESOTA, County of MOWER


At the corner location shown on the sketch:

☐ On 5-9-91 (DATE) found a monkey wrench setting vertical 4.5' below surface over a rotted post.

☐ left monument as found, ☐ lowered monument, ☐ removed monument (explain)

☐ On 5-9-91 (DATE) placed a cast iron monument on road surface at same location of of wrench found.

SKETCH OF REFERENCE TIES



JONES, HAUGH & SMITH INC.
Civil Engineers & Land Surveyors
Albert Lea, Minnesota

Statement of evidence relative to this corner location is on back of page.

I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.

_____ SIGNATURE 5-16-91 DATE

Registration No. 13807

☑ Land Surveyor, ☐ Professional Engineer

☐ County Surveyor, ☐ County Engineer

OFFICE OF THE COUNTY RECORDER

County of _____

I hereby certify that this document was filed in the County Rec. office at _____ .M. on the ____ day of _____ A.D., 19__

COUNTY RECORDER _____

By _____, Deputy

DOCUMENT NO. _____

M.H.D. FORM NO. 2105

STATEMENT OF EVIDENCE

W 1/4 corner Section 28-102-17

This corner was originally established by Deputy Surveyor William I. Anderson of the U.S. General Land Office in 1854. The government notes show a wood post and charred stake were set with a mound of earth and trench.

The following were contacted for section information:
Mower County Highway Department
Mower County Recorder
Zenk Engineering
Tucker Land Surveying

1930 Book "A" in the Mower County Engineering Office shows a corner at Sta. 161+39.6. The following ties were recorded:
50.1' SE to willow tree
34.8' SSE to willow tree
33.6' SW to rock
50.6' N to 4th F.P.

1991 Jones, Haugh & Smith Inc crew, under the direction of John H. Schulte, dug with the Mower County backhoe on centerline N-S-E-W road in line with N-S fences for bituminous overlay project #SAP 50-604-18. Excavated a 8' x 8' x 7' deep hole and uncovered a large sand deposit 3 feet wide and 6" long on road centerline. Appears corner may have been dug before. Continued digging and uncovered an old monkey wrench setting vertical 4.5' below surface over a rotted post bent over. Placed a cast iron monument on road surface at the same location of the wrench found.

The monument fits occupation and road centerlines within the section and is accepted as best evidence of a perpetuation of the original public land survey corner.