I hereby certify that this document and the data contained herein were prepared by me or under my direct supervision.

Steven J. Thompson 4-16-25
Date

Registration No. 22705

☒ Land Surveyor, ☐ Professional Engineer
☐ County Surveyor, ☐ County Engineer

MOWER COUNTY COORDINATES
NAD 83 (96) HARN
Northing=N156796.70 Latitude=N043°39'07.553771"
Easting=E743616.74 Longitude=W093°01'46.562051"

A687728

Office of the County Recorder
Mower County, Minnesota

I HEREBY CERTIFY THE WITHIN INSTRUMENT WAS FILED, AND/OR RECORDED ON 5/19/2025 9:17 AM

PACKAGE: 108323 REC FEE: $0.00

Sara Madison, Mower County Recorder

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

W1/4 Corner of Section 8, Township 102N Range 18W, 5th P.M.

STATE OF MINNESOTA, County of MOWER


At the corner location shown on the sketch

☐ On 2/26/2025 (DATE) found a CAST IRON MONUMENT

☒ left monument as found, ☐ lowered monument, ☐ removed monument (explain)

☐ On _____ (DATE) placed a _____

SKETCH OF REFERENCE TIES



NOT TO SCALE

JONES, HAUGH & SMITH INC
Civil Engineers & Land Surveyors
Albert Lea, Minnesota

Statement of evidence relative to this corner location is on back of page.

STATEMENT OF EVIDENCE

W1/4 Corner Section 8-T102N-R18W

The corner was originally established by Deputy Surveyor William I. Anderson of the U.S. General Land Office in July, 1854. At 2640 feet, set section corner post, deposited charcoal, raised mound of earth with trench and pits, as per instructions, and planted cherry NE locust SW.

December 21, 1998: Cast iron monument was set at corner location while conducting a survey in the N1/2 SW1/4 Section 8-T102N-R18W.

29 March 2001: JHS Crew searched are and found nothing. Original monument presumed to be destroyed by installation of box culvert. Used obliterated methods to restore corner position from occupation in adjoining section. Obliterated position is accepted to marking original location of Public Land Survey corner. Set cast iron monument at corner and made ties.

February 26, 2025: Jones, Haugh, & Smith crew recovered a cast iron monument. Checked existing ties and left cast iron monument in place and made ties.

For electronic survey data and analysis, contact the firm of Jones, Haugh and Smith Inc.


MONUMENT


EAST


NORTH