CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

EAST QUARTER Corner of Section 30, Township 103, Range 14, 5 P.M. "I" R. 110

STATE OF MINNESOTA, County of MOWER


At the corner location shown on the sketch:

On 5-1-87 found FOUND NOTHING

☐ left monument as found, ☐ lowered monument, ☐ removed monument (explain)

On 5-1-87 placed 3/4" X 24" PIPE & CAP STAMPED RJO 11009 AT FENCE EXTENSION INTERSECTION

SKETCH OF REFERENCE TIES



Statement of evidence relative to this corner location is on back of page

I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.

Ronald J. Olson (Signature) 7-30-87 (Date)

Registration No. 11009

☒ Land Surveyor ☐ Prof. Engineer
☐ County Surveyor ☐ County Engineer

Zenk·Read·Trygstad & ASSOCIATES, INC.
Engineers / Architects / Land Surveyors / Planners
Box 689, Albert Lea, MN 56007 507/373-0689

OFFICE OF THE COUNTY RECORDER
County of _____

I hereby certify that this document was filed in the County Recorders office at _____ .M. on the ____ day of _____ A.D., 19___.

County Recorder _____

By _____, Deputy

DOCUMENT NO. _____

Statement of Evidence:

EAST QUARTER CORNER SECTION 30, TOWNSHIP 103 NORTH, RANGE 14 WEST, 5 P.M.

Sept., 1853 — John Taylor, Deputy Surveyor, set 1/4 Sec. post and deposited a handful of charcoal. Raised a mound of earth and sod. Cut a trench and planted Osage Orange seeds E & W bet. pits & trench.

1987 — Jerry Schwarz, R.L.S. #13810, made an electronic survey and analysis of Section 29. No occupation lines were able to help determine the location of the corner.

1987 — Ronald J. Olson, R.L.S. #11009, searched the area with a magnetic locator and made an electronic survey of Section 30 to analize the occupation lines and help determine the location of the corner. An old fence line extended from the West 1/4 Corner easterly through the section to the area near the corner. The remains of an old fence line ran south from the area of the corner. A field division went east from the corner.

An analysis of the record and survey data gave no indication of monument perpetuation. The corner was set at the intersection of the fence line across Section 30 with the fence line south of the corner as evidence of the obliterated position. The area had been cultivated and was under 8 inches of water. The corner is 39.4 feet South and 35.2 feet East of the "Lost" location.

For details of the analysis and survey data contact Zenk, Read, Trygstad & Associates, Inc., Albert Lea, MN.