CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

NORTHEAST Corner of Section 31, Township 103, Range 14W, 5 P.M.

STATE OF MINNESOTA, County of MOWER


At the corner location shown on the sketch;

On 7-29-91 found A 1/2" REBAR IN CONC. MON. 2.8' FEET BELOW THE SURFACE.

☐ left monument as found, ☐ lowered monument, ☒ removed monument (explain)

On 7-29-91 placed A COUNTY CAP IN PLACE OF THE CONCRETE MONUMENT.

SKETCH OF REFERENCE TIES



Statement of evidence relative to this corner location is on back of page

I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.

Ronald J. Olson — Signature
12-31-91 — Date

Registration No. 11009

☒ Land Surveyor ☐ Prof. Engineer
☐ County Surveyor ☐ County Engineer

Zenk•Read•Trygstad & ASSOCIATES, INC.
Engineers/Architects/Land Surveyors/Planners
Box 689, Albert Lea, MN 56007 507/373-0689

OFFICE OF THE COUNTY RECORDER
County of _____

I hereby certify that this document was filed in the County Recorders office at _____.M. on the _____ day of _____ A.D., 19___.

County Recorder _____

By _____, Deputy

DOCUMENT NO. _____

NORTHEAST CORNER SECTION 31, TOWNSHIP 103 NORTH, RANGE 14 WEST, 5 PM

September, 1853 — John Ball, Deputy Surveyor, set post at corner. Deposited a handful of charcoal. Raised mound of earth and sod. Cut a trench and planted Osage Orange seeds SE, SW, NE and NW between pits and trench during the original Public Land Survey.

July 29, 1991 — Zenk Read Trygstad & Associates, excavated with a backhoe a trench 5 feet East to 5 feet West by 2.5 foot North to 2.5 South of the road centerlines by 4.5 feet deep and found a concrete monument 2.8 feet below the surface, 1 foot south of the east-west centerline and on the centerline to the south. The monument was removed during excavation.

An analysis of the record data shows no indication of the origin of the concrete monument. The monument agrees with the intersection of the township roads and is similar to others set by the County during section corner maintenance work. The monument is therefore accepted as marking the location of the original Public Land Survey Corner.