Index No. _____

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

W1/4 Corner of Section 36, Township 103N, Range 18W, 5th P.M.

STATE OF MINNESOTA, County of Mower


At the corner location shown on the sketch:

☒ On 5-3-91 (DATE) found a ½" diameter iron cast in center of 5" diameter concrete monument

☒ left monument as found, ☐ lowered monument, ☐ removed monument (explain)

☐ On _____ (DATE) placed a _____

SKETCH OF REFERENCE TIES



Statement of evidence relative to this corner location is on back of page.

I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.

_____ (SIGNATURE) 5-9-91 (DATE)

Registration No. 13807

☒ Land Surveyor, ☐ Professional Engineer

☐ County Surveyor, ☐ County Engineer

OFFICE OF THE COUNTY RECORDER

County of _____

I hereby certify that this document was filed in the County Rec. office at _____ .M. on the _____ day of _____ A.D., 19___

COUNTY RECORDER _____

By _____, Deputy

DOCUMENT NO. _____

M.H.D. FORM NO. 2105

STATEMENT OF EVIDENCE

W 1/4 corner Section 36-103-18

This corner was originally established by Deputy Surveyor William I. Anderson of the U.S. General Land Office in 1853. The government notes show a wood post was set with a mound of earth and trench.

The following were contacted for section corner information:
Mower County Highway Department
Mower County Recorder
Zenk Engineering
Tucker Land Surveying

The following information was obtained to support evidence of a perpetuation of the original public land survey corner.

1950 Recorded in Book "A" in the office of the Mower County Engineer shows a monument was found and ties taken.

1977 Jones, Haugh & Smith crew uncovered a 5" diameter concrete monument with 1/2" diameter iron cast in center during survey for Industrial Park plat.

1979 Jones, Haugh & Smith crew uncovered concrete monument during section breakdown of Section 36-103-18.

1991 Jones, Haugh & Smith Inc. crew uncovered a 5" diameter concrete monument in north-south fence. At the time of survey some difficulty was had in locating monument. An area resident covered monument with a large pile of stones and assumed he will recover after Jones, Haugh & Smith crew departs.

The monument agrees with past records and fits occupation and road centerlines and past surveys within the section and is accepted as a perpetuation of the original public land survey corner.