N¼ cor Sec 18-101-18

Cert. Filed 8-31-94 by JHS

Co. Grading plan shows Conc. Mon. @ EE sta 26+27

	Found	A	B
PK nail on surface		50.00	50.00
Mower Co. Mon.		50.11	49.91
Conc. Mon. 1.5 Down		50.04	49.96

Exc. trench 8' E-W x 5' N-S x 2' Deep w Backhoe. Found Conc. Mon. 1.5' below surface at the E x'n of CSAH 5 & Twp Rd N-S. The conc. mon. has been used and accepted as the PLS corner for 40+ yrs. Accepted Conc. Mon as marking position of orig. PLS corner. Placed CIM over Conc. Mon.

Aug. 31, 1994
60° Windy

SJT, KTW

(31) ✓

