SE cor SEC. 8 ★ 103-14

NO Information Found in
Mower Co. Corner Records

Mower Co. BACKHOE
JHS CREW Dug At Location
of Signal From Locator.
UNCOVERED 1" Shaft 1.8" Long
with CLAY TILE Chips Around
Shaft.
Left Shaft AS Found
SET 5/8" X 16" IRON with
CAST IRON MON. COVER Shaft
.60± BELOW Surface

8-14-6 JHS CREW FD CIM. TIE TO PP IS GOOD. SHOT FOR BASEMAP

10-10-02
CLOUDY
60°

HLS
EPE
FILM 60

