Index No. _____

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

N 1/4 Corner of Section 19 ,Township 101N Range 14W , 5th P.M.

STATE OF MINNESOTA, County of MOWER


At the corner location shown on the sketch

☐ On – (DATE) found a –

☐ left monument as found, ☐ lowered monument, ☐ removed monument (explain)

☐ On 11/23/98 (DATE) placed a 1/2"X24" PIPE

SKETCH OF REFERENCE TIES



JONES, HAUGH & SMITH INC
Civil Engineers & Land Surveyors
Albert Lea, Minnesota

Statement of evidence relative to this corner location is on back of page.

I hereby certify that this document and the data contained herein were prepared by me or under my direct supervision.

Cedric Schultz (SIGNATURE) 5/21/99 (DATE)

Registration No. 15229

☒ Land Surveyor, ☐ Professional Engineer

☐ County Surveyor, ☐ County Engineer

OFFICE OF THE COUNTY RECORDER

County of _____

I hereby certify that this document was filed in the County Rec. office at _____ .M. on the _____ day of _____ A.D., 19___

COUNTY RECORDER _____

By _____ , Deputy

DOCUMENT NO. _____

M.H.D. FORM NO. 2105

N 1/4 Cor Sec 19-101-14

This corner was originally established by Deputy Surveyor John Taylor of the U.S. General Land Office in 1853. The government notes show a wood post was set with mound of earth and trench.

The following were contacted for section corner information.

Mower County Highway Dept.
Mower County Recorder

No record of this corner was obtained from the above mentioned offices.

1999
Land Consultants personnel searched with a magnetic locator. This area was disturbed by construction equipment for placement of a driveway and culvert. This corner is reestablished at the intersection of a longstanding fence line to North and an overhead powerline and fence to East. Electronic measurements to adjoining land corners and property splits indicate that position is accepted as perpetuation of the Public Land Survey corner.

For electronic survey data and analysis, contact the firm of Land Consultants of Southern Minnesota, Inc.