Index No. _____

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

SW Corner of Section 26, Township 101N, Range 16W, 5TH P.M.

STATE OF MINNESOTA, County of MOWER


At the corner location shown on the sketch:

☐ On 6-4-93 (DATE) found a 6"ø x 18" CONC MONUMENT WITH IRON IN CNT

■ left monument as found, ☐ lowered monument, ☐ removed monument (explain)

☐ On 6-4-93 (DATE) placed a CAST IRON MONUMENT

SKETCH OF REFERENCE TIES



JONES, HAUGH & SMITH INC.
Civil Engineers & Land Surveyors
Albert Lea, Minnesota

Statement of evidence relative to this corner location is on back of page.

I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.

SIGNATURE _____ DATE 6-18-93

Registration No. 13807

☐ Land Surveyor, ☐ Professional Engineer

☑ County Surveyor, ☐ County Engineer

OFFICE OF THE COUNTY RECORDER
County of Mower

I hereby certify that this document was filed in the County Rec. office at 8 P.M. on the 25 day of June A.D., 1993

COUNTY RECORDER Harold Conger

By Marlene Marten, Deputy

DOCUMENT NO. 421748

Bk 80 Pg. 139

BOOK 80 PAGE 139

M.H.D. FORM NO. 2105

STATEMENT OF EVIDENCE

SW cor Sec 26-101-16

This corner was originally established by Deputy Surveyors Charles Phipps and Edward Fitzpatrick of the U.S. General Land Office in 1853. The government notes show a wood post was set with a mound of earth and trench.

The following were contacted for section corner information:
Mower County Highway Department
Mower County Recorder
Zenk Engineering
Tucker Land Surveying

The following information was obtained to support evidence of the perpetuation of the original public land survey corner.

1891 Clausen, Mower County Surveyor, notes indicate a stone at this corner.

1956 Mower County Highway Department Book 1 and the County State Aid Highway No. 6 Road Plans indicate a concrete monument inplace.

1993 Jones, Haugh & Smith Inc crew under the direction of John H. Schulte IV, RLS 13807, dug a 3'x2'x8' hole on the centerline centerline of County State Aid Highway No. 6 and Township Road No. T-67. We found a 6" diameter x 18" concrete monument with iron in center as said in County Road Plans. Therefore we accepted concrete monument found as the perpetuation of the public land survey corner and set a cast iron monument near road surface and above concrete monument found.

The monument found and cast iron monument set fits occupation lines within the section and is accepted as best evidence of a perpetuation of the original public land survey corner.