Index No. _____

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

NW Corner of Section 3, Township 101N Range 17W, 5TH P.M.

STATE OF MINNESOTA, County of MOWER


At the corner location shown on the sketch:

☐ On 5-20-93 (DATE) found a 5/8"ø x16" IRON

☐ left monument as found, ☐ lowered monument, ☐ removed monument (explain)

☐ On 5-20-93 (DATE) placed a CAST IRON MONUMENT

SKETCH OF REFERENCE TIES



JONES, HAUGH & SMITH INC.
Civil Engineers & Land Surveyors
Albert Lea, Minnesota

Statement of evidence relative to this corner location is on back of page.

I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.

SIGNATURE _____ DATE 6-9-93

Registration No. 13807

☐ Land Surveyor, ☐ Professional Engineer

☒ County Surveyor, ☐ County Engineer

OFFICE OF THE COUNTY RECORDER
County of Mower

I hereby certify that this document was filed in the County Rec. office at 11 A.M. on the 17 day of June A.D., 1993

COUNTY RECORDER Chandler Conger

By Marlene Martin, Deputy

DOCUMENT NO. 421534

Bk 79 Misc, Pg 580

M.H.D. FORM NO. 2105

BOOK 79 PAGE 580

STATEMENT OF EVIDENCE

NW cor Sec 3-101-17

This corner was originally established by Deputy Surveyor John Ball of the U.S. General Land Office in 1854. The government notes show a wood post was set with a mound of earth and trench.

The following were contacted for section corner information:
Mower County Highway Department
Mower County Recorder
Zenk Engineering
Tucker Land Surveying

The following information was obtained to support evidence of a perpetuation of the original public land survey corner.

1890 Clausen, Mower County Surveyor, notes indicate a government post at this corner and a distance of 39.94 chains west of the N 1/4 corner.

1972 Jones, Haugh & Smith Inc crew set a 5/8" diameter x 24" iron at the corner at the centerline centerline intersection of existing township roads.

1993 Jones, Haugh & Smith Inc crew under the direction of John H. Schulte IV, RLS 13807, dug a 5'x5'x12' hole on the centerline centerline of township road and found a 5/8" diameter x 24" iron six inches deep. Continued digging to a depth of virgin soil and found no evidence of the original public land survey corner. Therefore we replaced 5/8" diameter x 24" iron as found and set a cast iron monument near road surface and above monument found.

The monument set fits occupation lines within the section and is accepted as best evidence of a perpetuation of the original public land survey corner.

BOOK 79 PAGE 581