Index No. L-9

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

EAST QUARTER Corner of Section 17 ,Township 101 N ,Range 18 W , 5th P.M.

STATE OF MINNESOTA, County of MOWER

At the corner location shown on the sketch:

☐ On _____ (DATE) found a _____

☐ left monument as found, ☐ lowered monument, ☐ removed monument (explain)

☒ On 9-30-92 (DATE) Placed a 3/4" x 24" REBAR WITH ALUMINUM CAP STAMPED "DNR SURVEY MARKER", UP 0.2'

SKETCH OF REFERENCE TIES



NOTE:
SET STEEL WITNESS POST 1.0' NORTH OF MONUMENT

MONUMENT IS ON A BRUSHED LINE WEST TO RIVER

WOODS

60d SPIKE & DNR DISC
SW SIDE 10" BUR OAK
UP 1.0'

N 54° W
5.64'

S 74° E
21.10'

WOODS

S 88° W
37.50'

60d SPIKE & DNR DISC
SOUTH SIDE 9" BUR OAK
UP 1.0'

WOODS

60d SPIKE & DNR DISC
NORTH SIDE 9" WALNUT
UP 0.2'

BEARINGS OBSERVED WITH COMPASS

Statement of evidence relative to this corner location is on back of page.

J.B.M. OCT 92
WMA00548.00.00.01

I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.

Lowell R. Pomeroy Jr. 11-2-92
SIGNATURE DATE

Registration No. 17005

■ Land Surveyor, ☐ Professional Engineer

☐ County Surveyor, ☐ County Engineer

OFFICE OF THE COUNTY RECORDER 416856
County of Mower

I hereby certify that this document was filed in the Co. recorders office at 11 A.M. on the 3 day of Nov A.D., 1992

County Recorder Charles Enger

By Susan M. Davis ,Deputy

~~DOCUMENT NO.~~ Book 78 Misc Page 111

BOOK 78 PAGE 111

East Quarter Corner Section 17, Township 101 North, Range 18 West

The DNR Bureau of Engineering Contacted the following offices for information on this corner:

Mn Secretary of State
Mower County Recorder and Highway Engineer
Jones, Haugh & Smith Inc. at Albert Lea
Zenk-Read-Trygstad & Assoc. at Albert Lea
Tucker Land Surveying at Dexter

1854 U.S. General Land Office survey notes in the Secretary of State's Office show this corner marked with a post and marked the following bearing trees:

Red Oak 12 N 80 W 24 lks
Aspen 12 S 57 E 28 lks

1862 A subdivision of the East Half of the Southeast Quarter of Section 17, by Alanson B Vaughan, Surveyor, on file in the County Recorder's Office, shows a distance of 39.92 chains along the east line of said Southeast Quarter. No monumentation along this line is shown.

1964 The DNR Bureau of Engineering conducted a search for this, but found no evidence of a monument or occupation. Computed and used the lost position for this corner which measures 2638.69 ft. from adjoining section corners.

1992 July 30, the DNR Bureau of Engineering conducted a search for this corner at the position established in 1964, but found nothing. Searched for, but found no evidence of the government bearing trees. Contacted area landowner Wayne Hotson, who stated there is a tree to tree fence near the east-west quarter line os Section 17, but should NOT be considered to be on the line. It was put on the trees to make the fencing easier.
Computed the lost position for this corner and found it to measure 2638.83 ft. from adjoining section corners.

Analysis of the available information led the DNR Bureau of Engineering to conclude that the lost position marks the location of the corner.