Index No. _____

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

NW Corner of Section 16, Township 101N, Range 18W, 5th P.M.

STATE OF MINNESOTA, County of MOWER


At the corner location shown on the sketch:

☐ On 4-17-91 (DATE) found a cast iron monument 0.8' deep in new bituminous grade.

☐ left monument as found, ☐ lowered monument, ☐ removed monument (explain)

☐ On 4-17-91 (DATE) placed a cast iron monument flush with road surface over monument found.

SKETCH OF REFERENCE TIES



JONES, HAUGH & SMITH INC.
Civil Engineers & Land Surveyors
Albert Lea, Minnesota

Statement of evidence relative to this corner location is on back of page.

I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.

SIGNATURE _____ DATE 5-9-91

Registration No. 13807

☑ Land Surveyor, ☐ Professional Engineer

☐ County Surveyor, ☐ County Engineer

OFFICE OF THE COUNTY RECORDER
County of _____

I hereby certify that this document was filed in the County Rec. office at _____ .M. on the _____ day of _____ A.D., 19__

COUNTY RECORDER _____

By _____, Deputy

DOCUMENT NO. _____

M.H.D. FORM NO. 2105

STATEMENT OF EVIDENCE

NW corner Section 16-101-18

This corner was originally established by Deputy Surveyor William I. Anderson of the U.S. General Land Office in 1853. The government notes show a wood post and a charred stake were set with a mound of earth and trench.

The following were contacted for section corner information:
Mower County Highway Department
Mower County Recorder
Zenk Engineering
Tucker Land Surveying

No information was obtained to support evidence of a perpetuation of the original public land survey corner.

1991 Jones, Haugh & Smith Inc. crew under the direction of John Schulte dug with the County backhoe for 1991 Grading Project Mower County Highway Department Grading Project County State Aid Highway #5 SAP #50-605-10. Excavation uncovered a cast iron monument 0.8' below a new bituminous grade. Placed a cast iron monument flush with road surface over monument found.

The monument found was placed by MHD during a survey project on TH #105 1/4 mile more or less, east of corner. In 1976 a corner certificate was filed by Marlow McGowan RLS 11527 in Mower County Recorder's Office on this corner.

The monument fit occupation and road centerlines within the section and agrees with the 1976 corner certificate and is accepted as a perpetuation of the original public land survey corner.

Index No. _____

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

NORTHEAST Corner of Section 17, Township 101N, Range 18W, 5th P.M.

STATE OF MINNESOTA, County of MOWER


At the corner location shown on the sketch:

☒ On 6-25-76 (DATE) found a 7/8 INCH REINFORCING ROD (DOWN 1.9 FEET)

☒ left monument as found, ☐ lowered monument, ☐ removed monument (explain)

☒ On 7-1-76 (DATE) placed a MINNESOTA HIGHWAY DEPARTMENT CAST IRON MONUMENT (DOWN 0.1 FOOT)

SKETCH OF REFERENCE TIES



Statement of evidence relative to this corner location is on back of page.

I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.

Marlow R. McGowan 8/25/76
SIGNATURE DATE

Registration No. 11527

☒ Land Surveyor, ☐ Professional Engineer

☐ County Surveyor, ☐ County Engineer

OFFICE OF THE REGISTER OF DEEDS
County of _____

I hereby certify that this document was filed in the Reg. of Deeds office at _____ .M. on the _____ day of _____ A.D., 19 ___

Register of Deeds _____

By _____, Deputy

DOCUMENT NO. _____

BOOK 42 PAGE 514

MHD FORM NO. 21105

Statement of Evidence:

NORTHEAST CORNER SECTION 17, TOWNSHIP 101N, RANGE 18W, 5th P.M.

August, 1854 — Thomas L. Reyman, Deputy Surveyor, set post for the corner during the Original Public Land Survey.

1927 — Mower County Highway Department assumed the corner at the occupation lines and placed a concrete monument.

1961 — Mower County Highway Department regraded the road and recovered the concrete monument.

June 18, 1976 — Minnesota Highway Department found a 7/8 inch rebar down 1.9 feet (under the old road surface), probed under bar and hit the concrete monument.

The origin of the rebar is not of record. However, it monuments the corner as occupied for over 50 years. An analysis of the survey data indicates the rebar is in substantial harmony with PLS distances. Therefore, the bar is accepted as the Public Land Survey Corner.

For details of the survey data contact the District Office of Surveying and Mapping of the Minnesota Highway Department, Rochester.

4350

324350

Office of County Recorder
Mower County, Minnesota } SS

I hereby certify that the within instrument was filed for record on the 17 day of Aug A.D., 19 76 at 11 o'clock A. M. and duly recorded in Book 42 of Misc. on page 541

Charles Enger
CHARLES ENGER, COUNTY RECORDER

By Marlene Lou Deputy

BOOK 42 PAGE 542