Index No. _____

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

E 1/4 Corner of Section 18, Township 101N Range 18W, 5th P.M.

STATE OF MINNESOTA, County of MOWER


At the corner location shown on the sketch

☐ On 06/15/95 (DATE) found a MN DNR MONUMENT

☐ left monument as found, ☐ lowered monument, ☐ removed monument (explain)

☐ On 06/15/95 (DATE) placed a –

SKETCH OF REFERENCE TIES



JONES, HAUGH & SMITH INC
Civil Engineers & Land Surveyors
Albert Lea, Minnesota

BOOK 92 PAGE 34

Statement of evidence relative to this corner location is on back of page.

I hereby certify that this document and the data contained herein were prepared by me or under my direct supervision.

SIGNATURE _____ DATE 7-25-96

Registration No. 13807

☐ Land Surveyor, ☐ Professional Engineer

☒ County Surveyor, ☐ County Engineer

446679

OFFICE OF THE COUNTY RECORDER
County of Mower

I hereby certify that this document was filed in the County Rec. office at 9 a.M. on the 29th day of July A.D., 1996

COUNTY RECORDER Charles Enger
By _____, Deputy
DOCUMENT NO. 446679

M.H.D. FORM NO. 2105

Book 92 Page 34 Misc

E 1/4 Cor SEC 18-101-18

This corner was originally established by Deputy Surveyor William Anderson of the U.S. General Land Office in 1854. The government notes show a wood post was set with mound of earth and trench.

The following were contacted for section corner information.

Mower County Highway Dept.
Mower County Recorder
Zenk Engineering
Tucker Land Surveying

No record of this corner was obtained from the above mentioned offices.

1996 Jones Haugh and Smith crew, under direction of John Schulte, Mower County Surveyor RLS 13807, found Minnesota Department of Natural Resources monument 2' north of corner fence post. Accepted monument as a perpetuation of the original PLS corner.

The monument fits occupation and road centerlines within the section and is accepted as best evidence of a perpetuation of the original public land survey corner.

For electronic survey data and analysis, contact the firm of Jones, Haugh and Smith Inc.

Index No. L-5

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

EAST QUARTER Corner of Section 18, Township 101 N, Range 18 W, 5th P.M.

STATE OF MINNESOTA, County of MOWER


At the corner location shown on the sketch:

☐ On _____ (DATE) found a _____

☐ left monument as found, ☐ lowered monument, ☐ removed monument (explain)

☒ On 7-28-92 (DATE) Placed a 3/4" x 24" REBAR WITH ALUMINUM CAP STAMPED "DNR SURVEY MARKER", UP 0.5'

SKETCH OF REFERENCE TIES



Statement of evidence relative to this corner location is on back of page.

J.B.M. OCT 92
WMA00548.00.00.01

I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.

Lowell R. Pomerenke for 11-2-92
SIGNATURE DATE

Registration No. 17005

■ Land Surveyor, ☐ Professional Engineer

☐ County Surveyor, ☐ County Engineer

OFFICE OF THE COUNTY RECORDER 416854
County of Mower

I hereby certify that this document was filed in the Co. recorders office at 11 A.M. on the 3 day of Nov A.D., 1992

County Recorder Charles Enger

By Susan M. Davis, Deputy

~~DOCUMENT NO.~~ ~~Book 78 Misc Page~~ 107

BOOK 78 PAGE 107

East Quarter Corner Section 18, Township 101 North, Range 18 West

The DNR Bureau of Engineering Contacted the following offices for information on this corner:

Mn Secretary of State
Mower County Recorder and Highway Engineer
Jones, Haugh & Smith Inc. at Albert Lea
Zenk-Read-Trygstad & Assoc. at Albert Lea
Tucker Land Surveying at Dexter

1854 U.S. General Land Office survey notes in the Secretary of State's Office show this corner marked with a post, deposited charcoal, raised mound of earth with trench and pits as per instructions, planted cherry N.E. locust S.W.

1992 July 28, the DNR Bureau of Engineering conducted a search for the corner, but found on evidence of the government survey or a monument. Located the occupation in the area which consisted of a north-south fence and fence east. Established a position for this corner at the projected intersection of the above described fences. This position was found to measure:

5287.23 ft. from the east quarter corner Section 17
2651.05 ft. from the southeast corner Section 18

Analysis of the available information led the DNR Bureau of Engineering to conclude that the intersection of fences north-south and east marks the location of the corner.

BOOK '78 PAGE 108