Index No. _____

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

NORTH QUARTER Corner of Section 32 , Township 101N , Range 18W , 5TH P.M.

STATE OF MINNESOTA, County of MOWER


At the corner location shown on the sketch:

☒ On 4-28-09 (DATE) found a Cast Iron Monument, Flush.

☒ left monument as found, ☐ lowered monument, ☐ removed monument (explain)

☐ On _____ (DATE) placed a _____

SKETCH OF REFERENCE TIES



MOWER COUNTY COORDINATES

X=	746840.008
Y=	106615.436
NAD 83 (1996 ADJ.)	

Statement of evidence relative to this corner location is on back of page.

I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.

David A. Briggs — SIGNATURE — 7-27-09 — DATE

License No. 21199

☒ Land Surveyor ☐ Professional Engineer

☐ County Surveyor ☐ County Engineer

OFFICE OF THE COUNTY RECORDER

County of _____

I hereby certify that this document was filed in the Co. Recorder's office at _____ .M. on the ____ day of _____ A.D., 20 ___

County Recorder _____

By _____, Deputy

DOCUMENT NO. _____

RECEIVED
JUL 27 2009
BY: _____

Statement of Evidence:

NORTH QUARTER CORNER OF SECTION 32, TOWNSHIP 101N, RANGE 18W, 5P.M.

1854 to 1997	History is as shown on John H. Schulte Certificate of Location dated September 8, 1997 and recorded as Document 455945.
Marrch12, 2003	Mndot survey crew chief Dean Aarre found cast iron monument flush. Reference ties were updated.
April 28, 2009	Dave Griggs, Mndot surveyor, found the cast iron monument flush with the road surface. Reference ties were checked and updated.
	The cast iron monument is accepted as the best evidence of the public land survey corner.

Contact the Minnesota Department of Transportation Surveys Office in Rochester, Minnesota for more detailed information.

Index No. _____

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

S 1/4 Corner of Section 29, Township 101N Range 18W, 5th P.M.

STATE OF MINNESOTA, County of MOWER


At the corner location shown on the sketch

☐ On 03/04/1991 (DATE) found a 1/2" IRON IN CONC. MON.

☐ left monument as found, ☐ lowered monument, ☐ removed monument (explain)

☐ On 03/04/1991 (DATE) placed a 5/8" IRON

SKETCH OF REFERENCE TIES



JONES, HAUGH & SMITH INC
Civil Engineers & Land Surveyors
Albert Lea, Minnesota

BOOK 96 PAGE 261

Statement of evidence relative to this corner location is on back of page.

I hereby certify that this document and the data contained herein were prepared by me or under my direct supervision.

SIGNATURE _____ DATE 8-12-97

Registration No. 13807

☐ Land Surveyor, ☐ Professional Engineer

☒ County Surveyor, ☐ County Engineer

OFFICE OF THE COUNTY RECORDER
County of Mower

I hereby certify that this document was filed in the County Rec. office at 11 A.M. on the 8 day of Sept A.D., 1997

COUNTY RECORDER Charles Enger

By Susan M. Lawin, Deputy

DOCUMENT NO. 45548

M.H.D. FORM NO. 2105

Book 96 Misc Page 261

S 1/4 Cor SEC 29-101-18

This corner was originally established by Deputy Surveyor William Anderson of the U.S. General Land Office in 1854. The government notes show a wood post was set with mound of earth and trench.

The following were contacted for section corner information.

Mower County Highway Dept.
Mower County Recorder
Tucker Land Surveying

1976 Mower County Highway Dept. notes show concrete monument at this location.

1976 Jones Haugh and Smith crew located a 1/2" iron in concrete 1.5' deep. Placed a 5/8" iron over monument found.

1991 Jones Haugh and Smith crew, under direction of John Schulte, Mower County Surveyor RLS 13807, dug by hand at the CL of CSAH No. 6 and in line with line fence north and located a aluminum monument in agreement with 1976 ties.

The monument fits occupation and road centerlines within the section and is accepted as best evidence of a perpetuation of the original public land survey corner.

For electronic survey data and analysis, contact the firm of Jones, Haugh and Smith Inc.