Index No. _____

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

NE Corner of Section 2, Township 102N, Range 16W, 5th P.M.

STATE OF MINNESOTA, County of mower


At the corner location shown on the sketch:

☐ On 5-10-91 (DATE) found a 10"øx18"concrete monument with 3/4"ø iron in center.

☐ left monument as found, ☐ lowered monument, ☐ removed monument (explain)

☐ On 5-10-91 (DATE) placed a cast iron monument over concrete monument found.

SKETCH OF REFERENCE TIES



JONES, HAUGH & SMITH INC.
Civil Engineers & Land Surveyors
Albert Lea, Minnesota

Statement of evidence relative to this corner location is on back of page.

I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.

_____ SIGNATURE 5-16-91 DATE

Registration No. 13807

☐ Land Surveyor, ☐ Professional Engineer

☐ County Surveyor, ☐ County Engineer

OFFICE OF THE COUNTY RECORDER

County of _____

I hereby certify that this document was filed in the County Rec. office at _____ .M. on the ____ day of _____ A.D., 19__

COUNTY RECORDER _____

By _____, Deputy

DOCUMENT NO. _____

M.H.D. FORM NO. 2105

STATEMENT OF EVIDENCE

NE corner Section 2-102-16

This corner was originally established by Deputy Surveyor John Ball of the U.S. General Land Office in 1853. The government notes show a wood post and two stones were set with a mound of earth and trench.

The following were contacted for section information:
Mower County Highway Department
Mower County Recorder
Zenk Engineering
Tucker Land Surveying

The following information was obtained to support evidence of a perpetuation of the original public land survey corner:

1891 Clausen Mower County Surveyor notes from 1880-1892 show a stone inplace.

1980 Jones, Haugh & Smith Inc crew uncovered corner during a complete section survey of Section 2-102-16. No record was made of the monument found.

1991 Jones, Haugh & Smith Inc crew, under the direction of John H. Schulte, dug with the County backhoe on centerline centerline of N-S-E-W roads for bituminous overlay project 50-613-08. Dug a 4' x 10' x 3' deep hole and uncovered a 10" diameter x 18" long concrete monument with a 3/4" diameter iron cast in the center 3' below surface in virgin soil. Placed a cast iron monument on road surface over the concrete monument found.

The monument fits occupation and road centerlines within the section and is accepted as best evidence of a perpetuation of the original public land survey corner.