Index No. _____

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

N1/4 Corner of Section 21, Township 102N Range 16W, 5TH P.M.

STATE OF MINNESOTA, County of MOWER


At the corner location shown on the sketch:

☐ On 5-20-93 (DATE) found a 2"×2"×12" PIECE OF OLD CORNER FENCE POST WITH A 6"ø LOOP OF BARBED WIRE LAYING NEXT TO POST

☐ left monument as found, ☐ lowered monument, ☐ removed monument (explain)

☐ On 5-20-93 (DATE) placed a CAST IRON MONUMENT

SKETCH OF REFERENCE TIES



JONES, HAUGH & SMITH INC.
Civil Engineers & Land Surveyors
Albert Lea, Minnesota

Statement of evidence relative to this corner location is on back of page.

I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.

_____ 5-25-93
SIGNATURE DATE

Registration No. 13607

☐ Land Surveyor, ☐ Professional Engineer

☑ County Surveyor, ☐ County Engineer

OFFICE OF THE COUNTY RECORDER
County of Mower

I hereby certify that this document was filed in the County Rec. office at 11 A.M. on the 26 day of MAY A.D., 1993

COUNTY RECORDER Amanda Enman

By Marlene Martin, Deputy

DOCUMENT NO. 421014

Book 79 Misc Pg 475

M.H.D. FORM NO. 2105

BOOK 79 PAGE 475

STATEMENT OF EVIDENCE

N 1/4 corner Section 21-102-16

This corner was originally established by Deputy Surveyor John Quigley of the U.S. General Land Office in 1853. The government notes show a wood post was set with a mound of earth and trench.

The following were contacted for section corner information:
Mower County Highway Department
Mower County Recorder
Zenk Engineering
Tucker Land Surveying

The following information was obtained to support evidence of a perpetuation of the original public land survey corner.

1993 Jones, Haugh & Smith Inc crew under the direction of John H. Schulte IV, Reg. No. 13807, dug a 5'x4'x15' long hole on the centerline of the east-west township road and in line with north-south fences. We dug to a depth of 4 feet which was virgin soil and uncovered a 2"x2"x12" piece of old wood corner post with a 6" diameter barbed wire loop laying next to post found. Location of post found was in centerline of east-west township road and also in line with north-south line fences. Placed a cast iron monument over location of post and barbed wire found near the road surface.

The monument set fits occupation lines within the section and is accepted as best evidence of a perpetuation of the original public land survey corner.