Index No. _____

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

SW Corner of Section 21, Township 102N Range 16W, 5TH P.M.

STATE OF MINNESOTA, County of MOWER


At the corner location shown on the sketch:

☐ On 5-20-93 (DATE) found a 8" x 8" x 18" POINTED FIELD STONE & A 2"x2"x4" BRICK LAYING ON EAST SIDE OF STONE

☐ left monument as found, ☐ lowered monument, ☐ removed monument (explain)

☐ On 5-20-93 (DATE) placed a CAST IRON MONUMENT

SKETCH OF REFERENCE TIES



JONES, HAUGH & SMITH INC.
Civil Engineers & Land Surveyors
Albert Lea, Minnesota

Statement of evidence relative to this corner location is on back of page.

I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.

SIGNATURE _____ DATE 5-25-93

Registration No. 13807

☐ Land Surveyor, ☐ Professional Engineer

☑ County Surveyor, ☐ County Engineer

OFFICE OF THE COUNTY RECORDER
County of Mower

I hereby certify that this document was filed in the County Rec. office at 11 A.M. on the 26 day of May A.D., 1993

COUNTY RECORDER Amanda Engo

By Marlene Martin, Deputy

DOCUMENT NO. 421012
Book 79 Misc Pg 471

M.H.D. FORM NO. 2105

BOOK 79 PAGE 471

STATEMENT OF EVIDENCE

SW corner Section 21-102-16

This corner was originally established by Deputy Surveyor John Quigley of the U.S. General Land Office in 1853. The government notes show a wood post was set with a mound of earth and trench.

The following were contacted for section corner information:
Mower County Highway Department
Mower County Recorder
Zenk Engineering
Tucker Land Surveying

The following information was obtained to support evidence of a perpetuation of the original public land survey corner.

1888 Clausen, Mower County Surveyor, indicates a government corner at the southeast corner of Section 20-102-16.

1892 Clausen, Mower County, Surveyor, indicates an iron bolt at the northeast corner of Section 29-102-16.

1993 Jones, Haugh & Smith Inc crew under the direction of John H. Schulte IV, Reg. No. 13807, dug a 4'x2'x10' long hole on the centerline centerline of the east-west and north-south township roads. We found an 8"x12"x18" pointed field stone resting in virgin soil with a 2"x2"x4" piece of brick resting on the east side of the stone found. Therefore we accepted stone and brick found as the best evidence of a perpetuation of the original public land survey corner and set a cast iron monument near road surface above monuments found.

The monument set fits occupation lines within the section and is accepted as best evidence of a perpetuation of the original public land survey corner.