Index No. _____

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

W 1/4 Corner of Section 5, Township 102N Range 17W, 5th P.M.

STATE OF MINNESOTA, County of MOWER


At the corner location shown on the sketch

☐ On 04/25/2000 (DATE) found a MOWER CO. HWY. DEPT. ALUMINUM MONUMENT

☒ left monument as found, ☐ lowered monument, ☐ removed monument (explain)

☐ On _____ (DATE) placed a _____

SKETCH OF REFERENCE TIES



JONES, HAUGH & SMITH INC
Civil Engineers & Land Surveyors
Albert Lea, Minnesota

Statement of evidence relative to this corner location is on back of page.

I hereby certify that this document and the data contained herein were prepared by me or under my direct supervision.

_____ (SIGNATURE) 5-16-00 (DATE)

Registration No. 13807

☐ Land Surveyor, ☐ Professional Engineer

☒ County Surveyor, ☐ County Engineer

OFFICE OF THE COUNTY RECORDER
County of _____

I hereby certify that this document was filed in the County Rec. office at _____ .M. on the _____ day of _____ A.D., 19___

COUNTY RECORDER _____

By _____, Deputy

DOCUMENT NO. _____

M.H.D. FORM NO. 2105

W 1/4 Cor Sec 5-102-17

This corner was originally established by Deputy Surveyor Charles Phipps and Edward Fitzpatrick of the U.S. General Land Office in 1854. The government notes show a wood post was set with mound of earth and trench.

The following were contacted for section corner information.

Mower County Highway Dept.
Mower County Recorder
Tucker Land Surveying

1957 Mower County records state an iron was in place.

1973 Mower Co. Highway Dept. personnel located this corner during regrading project, and reset it after grading project was completed.

1993 Jones Haugh and Smith crew, under direction of John Schulte, Mower County Surveyor RLS 13807, found an aluminum monument at this location.

2000 Jones Haugh and Smith crew, under direction of John Schulte, Mower County Surveyor RLS 13807, found an aluminum monument at this location.

The monument fits occupation and road centerlines within the section and is accepted as best evidence of a perpetuation of the original public land survey corner.

For electronic survey data and analysis, contact the firm of Jones, Haugh and Smith Inc.

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

EAST QUARTER Corner of Section 6, Township 102N, Range 17W, 5 P.M.

STATE OF MINNESOTA, County of MOWER


At the corner location shown on the sketch:

On 9-4-90 found 1/2" BAR (REMOVED DURING EXCAVATION)

☐ left monument as found, ☐ lowered monument, ☒ removed monument (explain)

On 9-4-90 placed 3/4" REBAR AND COUNTY CAP

SKETCH OF REFERENCE TIES



Statement of evidence relative to this corner location is on back of page

I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.

Ronald A. Olson — Signature

11-6-90 — Date

Registration No. 11009

☒ Land Surveyor ☐ Prof Engineer

☐ County Surveyor ☐ County Engineer

OFFICE OF THE COUNTY RECORDER

County of _____

I hereby certify that this document was filed in the County Recorders office at _____ .M. on the _____ day of _____ A.D., 19___.

County Recorder _____

By _____, Deputy

DOCUMENT NO. _____

STATEMENT OF EVIDENCE

East Quarter Corner Section 6, Township 102 North, Range 17 West, 5th P.M.

September, 1854	William Anderson, Deputy Surveyor, set post at quarter section corner during the original Public Land Survey.
1957	Page 20 of Mower County Surveyors Record shows ties to monument.
1972	Mower County Engineers Plans show ties to monument.
September 4, 1990	Zenk Read Trygstad & Associates, Inc. excavated with a backhoe, a trench 4 feet North to 3 feet South of center line and 4 feet west to 4 feet east of the fence line to the North and 4.5 feet deep and found a 1" bar 2.8 feet below the surface on center line. An analysis of the record shows no indication of the origin of the bar. The bar agrees with the occupation lines and has been maintained by the County as the corner for over 33 years. The bar is accepted as marking the location of the original Public Land Survey Corner.