Index No. _____

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

W1/4 Corner of Section 27, Township 102N, Range 17W, 5th P.M.

STATE OF MINNESOTA, County of MOWER


At the corner location shown on the sketch:

☐ On 5-7-91 (DATE) found a harrison cast iron monument over a 5"Ø concrete monument in clay tile.

☐ left monument as found, ☐ lowered monument, ☐ removed monument (explain)

☐ On 5-7-91 (DATE) placed a cast iron monument over concrete monument found.

SKETCH OF REFERENCE TIES



Statement of evidence relative to this corner location is on back of page.

I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.

SIGNATURE _____ DATE 5-9-91

Registration No. 13807

☒ Land Surveyor, ☐ Professional Engineer

☐ County Surveyor, ☐ County Engineer

OFFICE OF THE COUNTY RECORDER

County of _____

I hereby certify that this document was filed in the County Rec. office at _____ .M. on the ____ day of _____ A.D., 19__

COUNTY RECORDER _____

By _____, Deputy

DOCUMENT NO. _____

M.H.D. FORM NO. 2105

STATEMENT OF EVIDENCE

W 1/4 corner Section 27-102-17

This corner was originally established by Deputy Surveyor William I. Anderson of the U.S. General Land Office in 1853. The government notes show a charred stake was set with a mound of earth and trench.

The following were contacted for section corner information:
- Mower County Highway Department
- Mower County Recorder
- Zenk Engineering
- Tucker Land Surveying

The following information was obtained to support evidence of a perpetuation of the original public land survey corner.

1930 County Grading Plan SAH #20 shows a monument inplace and ties taken and recorded in Book "A" in the office of the County Engineer.

1951 Revised notes in Book "A", a concrete monument was uncovered and new ties were taken.

1991 Jones, Haugh & Smith crew, under the direction of John H. Schulte, dug with the County backhoe on the centerline of County Roads and uncovered a harrison cast iron monument 2' below road surface. Continued digging and uncovered a 6" diameter clay tile with 1/2 diameter iron cast in concrete in the center of the tile. Left monument as found and placed cast iron monument over it on the road surface.

The monument agrees with past records and fits occupationand road centerlines within the section and is accepted asbest evidence of a perpetuation of the original publicland survey corner.